




GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
January 31, 2013

Reviewed: 

Mine Name: Morgan Facility	Permit Number: M/029/0008
Operator Name: Geneva Rock Products, Inc.	Inspection Date: November 13, 2010
Inspector(s): L Heppler	Time: 2:00 PM
Other Participants: none	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 04-04-2015 **Bond Amount:** \$450,000 **Permit fee** is up to date

Purpose of Inspection: Routine annual Inspection. This was the first documented site visit and inspection for the mine.

Inspection Summary: An LMO had been submitted for the mine at the time of the site visit, but not approved until April 26, 2011. On March 8, 2012 the permit was transferred to Geneva Rock Products. Geneva is now solely responsible to conduct mining and reclamation as outlined in the LMO NOI. No topsoil stockpiles were noted on site. Every effort should be made to salvage top soil from the site prior to mining. Photos were taken to document site conditions, including historic kilns on site.

Conclusions and Recommendations: The Operator will have difficulty with revegetation, due to lack of topsoil from the 2 prior small mining operations, but with proper planning in the future revegetation is still possible. The Operator should start developing a growth medium stockpile. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:eb

cc: Geneva Rock Product – Brent Sumison

O:\M029-Morgan\M0290008-MorganFacility\inspections\Insp-11032010.doc





Historic Kiln



Historic Kiln



Historic monument



Natural hillside prior to mining



Scale house



Upper pit with highwall



Lower slope with Russian Thistle



High pressure gas line